



Figure 1051.515-1: Flow Chart of Permeation Test Procedure with and without DF Determination

## 1: Full Test Procedure

## 2: Base Test with DF\*



\* The deterioration factor (DF) is the difference between the baseline and final permeation test runs in the full test procedure.

\*\* This soak time can be shortened based on the length of "soak" during durability testing.